



Dimensions



Code	A	B	C	D	E	F	G	Wt (lb)
600064A	1" MNPT	6¼"	11"	6"	5½"	7"	4"	7.3
600069A	1" sweat	4¾"	10¼"	5½"	5½"	7"	4"	7.3
600066A	1" press	7"	11 ³ / ₈ "	6 ³ / ₈ "	5½"	7"	4"	7.3
600074A	1¼" MNPT	7¼"	11 ⁷ / ₈ "	6¼"	5½"	7"	4"	8.2
600079A	1¼" sweat	5¾"	11 ¹ / ₈ "	5½"	5½"	7"	4"	8.2
600076A	1¼" press	9¾"	13 ¹ / ₈ "	7½"	5½"	7"	4"	8.2
600084A	1½" MNPT	9 ¹ / ₈ "	14 ³ / ₈ "	9½"	5½"	7"	4"	21.0
600089A	1½" sweat	7 ⁷ / ₈ "	13 ¹ / ₈ "	8¼"	5½"	7"	4"	21.0
600086A	1½" press	10 ¹ / ₈ "	14 ⁷ / ₈ "	10"	5½"	7"	4"	21.0
600094A	2" MNPT	9½"	14½"	7 ⁵ / ₁₆ "	5½"	7"	4"	22.0
600099A	2" sweat	8"	13 ¹¹ / ₁₆ "	6½"	5½"	7"	4"	22.0
600096A	2" press	13¾"	16 ⁵ / ₈ "	9 ⁷ / ₁₆ "	5½"	7"	4"	22.0

Code	connections	A	B	C	D	E	F	G	H/I	Wt (lb)
600066AS	1" copper	24¾"	7½"	8¼"	5¼"	35¼"	32"	39"	3½"	27.3
600076AS	1¼" copper	27"	7½"	9"	6¼"	39¼"	36"	43"	3½"	28.2
600086AS	1½" copper	33¾"	8½"	13¼"	5"	43¼"	40"	48"	4"	41
600096AS	2" copper	36¾"	8 ⁷ / ₈ "	14¼"	5 ⁵ / ₈ "	47¼"	50"	60"	5"	42

For press models,

Lay lengths: size 1"-5½"; size 1¼"- 7¾"; size 1½"- 7³/₈"; size 2"-10¾".